COFC

DE 0 6 2004 &

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

Patentees:	Raymond M. Hauser)	
Patent No.:	6,817,430 BZ)	Examiner: Lesley D. Morris
	,)	Group Art Unit: 3611
Date of Patent:	November 16, 2004)	Docket No.: 36400.29US2
Title:	Connection Apparatus For A)	Docket No.: 30400.29052
	Transaxle Assembly Having)	
	Two Housings)	

REQUEST FOR CERTIFICATE OF CORRECTION

Certificate of Correction Branch Commissioner for Patents P.O. Box 1450 Alexandria, VA 22313-1450

Dear Sir:

Certificate
DEC 2 7 2004

of Correction

ECEIVED ECEIVED
RECEIVED
JAN 1 4 2005

GROUP 3600

Upon reviewing the above-referenced Letters Patent, it was determined that a mistake was made during the printing of the Patent by the Patent and Trademark Office. This mistake was made by the Office and through no fault of the Patentees. Therefore, it is believed that no fees are required. If it is deemed that any fees are required, please charge any fee deficiency to deposit account number 502,261. Please contact the undersigned attorney if there are any questions.

Dated: December 1, 2004

Respectfully submitted,

Thomas C. McDonough
Registration No.: 33,734
Neal Gerber and Eisenberg LLP
2 North Le Selle Street

2 North LaSalle Street Chicago, Illinois 60602

Certificate of Mailing

The undersigned hereby certifies that this Transmittal Letter and its enclosures are being deposited with the United States Postal Service, as first class mail, in an envelope addressed to: Certificate of Correction Branch, Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450 on December 1, 2004.

Under the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number. (Also Form PTO-1050)

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO : 6,817,430 \$ 2

DATED

: November 16, 2004

INVENTOR(S):

Raymond M. Hauser

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Col. 4, line 34

replace "with at least one output shall extending from the housing." with --with at least one output shaft extending from the housing.--.

MAILING ADDRESS OF SENDER:

PATENT NO. 6,817,430

Thomas C. McDonough Neal, Gerber & Eisenberg 2 North LaSalle Street Chicago, Illinois 60602

No. of additional copies

This collection of information is required by 37 CFR 1.322, 1.323, and 1.324. The information is required to obtain or retain a benefit by the public which is to file (and by the USPTO to process) an application. Confidentiality is governed by 35 U.S.C. 122 and 37 CFR 1.14. This collection is estimated to take 1.0 hour to complete, including gathering, preparing, and submitting the completed application form to the USPTO. Time will vary depending upon the individual case. Any comments on the amount of time you require to complete this form and/or suggestions for reducing this burden, should be sent to the Chief Information Officer, U.S. Patent and Trademark Office, U.S. Department of Commerce, P.O. Box 1450, Alexandria, VA 22313-1450. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Attention Certificate of Corrections Branch, Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450.